MATERIAL SAFETY DATA SHEET
This MSDS complies with OSHA'S Hazard Communication Standard 29 CFR 1910.1200 and OSHA Form 174

	IDENTITY AND MANUF	ACTU	RER'S INFORMATI	ON				
NFPA Rating: Health-1;	<u> </u>							
Manufactured For:	Triple S	DOT	DOT Hazard Classification: ORM-D					
Address:	2 Executive Park Dr.	Identity (trade name as used on label):						
Address:							225	
With Spray Thru Cap								
Phone: 978-667-7900			MSDS Number: A00239WF Revision-5B (extremely flammable)					
			Date Prepared: 03/20/10 (02/01/07) Prepared By: TR / IB					
NOTICE: JUDGEMENT BASED ON INDIRECT TEST DATA Information Calls: 978-667-7900								
SECTION 1 - MATERIAL IDENTIFICATION AND INFORMATION								
COMPONENTS-CHEMIC	CAL NAMES AND COMMON NAMES		CAS Number	SARA	OSHA PEL	ACGIH	Carcinogen	
(Hazardous Components 1% or greater; Carcinogens 0.1% or greater)				III LIST	(ppm)	TLV (ppm)	Ref. Source **	
ACETONE			67-64-1	No	1000	750	d	
ISOBUTANE / PROPANE BLEND			75-28-5	No	800	800	d	
			74-98-6	No	1000	1000	d	
SECTION 2 - PHYSICAL/CHEMICAL CHARACTERISTICS								
Boiling Point: N/A Specific Gravity (H2O=1): Concentrate Only = < 1								
							e): N/A	
Vapor Density (Air =		Evaporation Rate (= 1): N/E						
	,	• ,						
Solubility in Water: Soluble Water Reactive: No								
Appearance and Odor: Clear liquid with fragrance.								
SECTION 3 - FIRE AND EXPLOSION HAZARD DATA FLAMMABILITY as per USA FLAME PROJECTION TEST (aerosols): flame								
projection with spray through cap: projection greater than 18" with flashba			N/E		Volume:			
Categorized as EXTRI		% LEL: N/E % UEL: N/E						
FLASH POINT AND METHOD USED (non-aerosols): N/A SPECIAL FIRE FIGHTING PROCEDURES: Provide shielding for personnel. Wear								
EXTINGUISHER MEDIA: Foam, dry chemical, carbon dioxide, self-contained breathing apparatus. Cool containers with water fog to prevent								
water. rupturing & spewing.								
Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 120°F or the container may rupture.								
SECTION 4 - REACTIVITY HAZARD DATA								
STABILITY [X] STABLE [] UNSTABLE HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT OCCUR								
Incompatibility (Mat. to avoid): Alkalis, oxidizing materials, amines. Conditions to Avoid: Open flame, welding arcs, heat.								
Hazardous Decomposition Products: CO, CO2.								
SECTION 5 - HEALTH HAZARD DATA								
PRIMARY ROUTES OF ENTRY: [X]INHALATION []INGESTION []SKIN ABSORPTION []EYE []NOT HAZARDOUS								
ACUTE EFFECTS Vapor concentrations around 1000 ppm may cause slight transient irritation to the upper respiratory tract.								
Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible								
innalation: Excessive innalation of vapors can be narmful and may cause neadache, dizziness, asphyxia, anesthetic effects and possible unconsciousness.								
Eye Contact: Irritation. Skin Contact: May cause slight irritation.								
Ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea. CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause mucous membrane irritation, overnight								
headache, and general weakness.								
Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, skin, or upper respiratory conditions.								
EMERGENCY FIRST AID PROCEDURES								
Eye Contact: Flush with water for 15 minutes. If irritated, seek medical attention.								
Skin Contact: Wash with soap and water. If irritated, seek medical attention.								
Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention.								
Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention.								
SECTION 6 - CONTROL AND PROTECTIVE MEASURES								
Respiratory Protection	on (specify type): If vapor concentration exceeds					of Mines / N	IOSH for organic	
vapor.	(opening sype) raper consecutation exceeds	,	acc respirator appre			0	. c c c . ga c	
	atex, if skin easily irritated.	Eve l	Protection: Safety	alasses	recommend	ed		
Protective Gloves: Latex, if skin easily irritated. Eye Protection: Safety glasses recommended.								
Other Protective Clothing & Equipment: None								
Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing.								
SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE								
Steps To Be Taken If Material Is Spilled Or Released: Absorb with suitable medium. Incinerate or landfill according to local, state or federal								
regulations. DO NOT FLUSH TO SEWER.								
Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure through normal use, pose no disposal hazard.								
Precautions To Be Taken In Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 120°F.								
Other Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Avoid breathing vapors. Remove								
ianition sources.						-		

We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.

** Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only