

MATERIAL SAFETY DATA SHEET  
OSHA'S HAZARD COMMUNICATION STANDARD – U.S. DEPARTMENT OF LABOR

29 CFR 1910.1200

OMB NO.: 1218-0072

**SECTION 1 – PRODUCT IDENTIFICATION**

IDENTITY: **LEMON OIL FURNITURE**

MANUFACTURER'S NAME: Genlabs (Formerly General Chemical Corp.)  
ADDRESS: 5568 Schaefer Ave

CITY: Chino

STATE: CA

EMERGENCY PHONE: 800-424-9300  
ZIP: 91710

PHONE: 909-591-8451  
DATE PREPARED: 1/21/99

**SECTION 2 – HAZARDOUS INGREDIENTS/IDENTITY INFORMATION**

HAZARDOUS COMPONENTS	CAS#	OSHA PEL	ACGIH TLV	WEIGHT %
Distillates, Hydrotreated Light	64742478	400ppm	400ppm	

VOC Content: Exempt g/L

NOTE:

**SECTION 3 – PHYSICAL/CHEMICAL CHARACTERISTICS**

BOILING POINT (°F): >212	SPECIFIC GRAVITY: .839	VAPOR PRESSURE: Not Tested
MELTING POINT (°F): Not Tested	EVAPORATION RATE: Not Tested	VAPOR DENSITY: Not Tested
SOLUBILITY IN WATER: Insoluble%	APPEARANCE AND ODOR: YELLOW/LEMON ODOR	

**SECTION 4 – FIRE AND EXPLOSION HAZARD DATA**

FLASH POINT (°F): 226	FLAMMABLE LIMITS: Not Tested	LEL: 0.6	UEL: 6.0	pH: Not Tested	DOT #: Combustible
NFPA HAZARD RATING: (0-Lease, 4-Extreme)	H F R S 1 1 0 0	EXTINGUISHING MEDIA: CO2, Dry Foam	SPECIAL FIRE FIGHTING PROCEDURE: None		

UNUSUAL FIRE AND EXPLOSION HAZARDS: None

**SECTION 5 – REACTIVITY DATA**

STABILITY: Stable  
CONDITIONS TO AVOID: None  
INCOMPATIBLE MATERIALS TO AVOID: Water, Strong Oxidizers  
HAZARDOUS DECOMPOSITION OR BYPRODUCTS: CO, CO2  
HAZARDOUS POLYMERIZATION: None  
CONDITIONS TO AVOID: None

**SECTION 6 – HEALTH HAZARD DATA**

**ROUTE OF ENTRY**

INHALATION?: Possible SKIN?: Possible INGESTION?: Possible

HEALTH HAZARDS: Same as signs and symptoms of exposures.

NOTE: All chemicals incorporated into this product are found on the TSCA inventory list.

OSHA CARCINOGENICITY?: None NTP?: None IARC MONOGRAPHS?: None

**SIGNS AND SYMPTOMS OF OVER EXPOSURE**

EYES: Burning Sensation SKIN: Irritant INGESTION: Toxic, Do not induce vomiting, call physician INHALATION: Dizziness, Headaches, Irritation

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE: Same as signs and symptoms of over exposure.

**EMERGENCY AND FIRST AID PROCEDURES**

EYES: Flush with water for 15 minutes. If irritation persists, call physician

SKIN: Wash off with soap & water

INGESTION: Do not induce vomiting, call physician

INHALATION: Get person fresh air if unconscious, call physician

**SECTION 7 – PRECAUTIONS FOR SAFE HANDLING AND USE**

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Soak up with inert, absorbant material. Scoop up and place in a proper waste disposal container.

WASTE DISPOSAL METHOD: Dispose of in accordance with state and local regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Store in a cool, dry place, out of direct sunlight. Do not freeze or heat above 110 °F

OTHER PRECAUTION: Keep out of reach of children. Follow directions on the container for proper use of this product.

**SECTION 8 – CONTROL MEASURES**

RESPIRATORY PROTECTION: Open all doors and windows. If exposure is above TLV or PEL, a NIOSH approved respirator equipped for the exposure or suitable respiratory protection per 29 CFR 1910.134, is required.

**VENTILATION**

LOCAL EXHAUST: If Available MECHANICAL: If Available SPECIAL: None OTHER: None

PROTECTIVE GLOVE: Plastic/Rubber, Chemical Resistant EYE PROTECTION: Glasses/Goggles

OTHER PROTECTIVE CLOTHING OR EQUIPMENT: None

WORK HYGENIC PRACTICES: Use common sense and care around chemicals. Never mix chemicals. Consult your supervisor for other practices. All practices depend on your specific business. Directions for use are normally found on label which will dictate engineering and control measures.

OTHER SPECIAL REQUIREMENTS: