## **MATERIAL SAFETY DATA SHEET**

This MSDS complies with OSHA'S Hazard Communication Standard 29 CFR 1910.1200 and OSHA Form 174

	The mede complies that consider a community		Otaliaala 20 Olit 101	011200 011	a 00111111 0111			
IDENTITY AND DISTRIBUTOR'S INFORMATION								
NFPA Rating: Health-1; Flammability-3; Reactivity-0; Special HMIS Rating: Health-1; Flammability-3; Reactivity-0; Personal Protection-B							al Protection-B	
Manufactured For:	Triple S	_	DOT Hazard Classification: ORM-D					
Address:	2 Executive Park Dr.	ldent	Identity (trade name as used on label):					
Address:	Billerica, MA 01862		SSS Mountain Fresh Air Deodorizer #05225					
			MSDS Number: A00239NF WF Revision-5 (NF)					
		Date Prepared: 02/01/07 Prepared By: TR / IB						
NOTICE: JUDGEMENT BASED ON INDIRECT TEST DATA Information Calls: 978-667-7900								
SECTION 1 - MATERIAL IDENTIFICATION AND INFORMATION								
	CAL NAMES AND COMMON NAMES		CAS Number	SARA	OSHA PEL	ACGIH	Carcinogen	
(Hazardous Components 1% or greater; Carcinogens 0.1% or greater)  ACETONE			07.04.4	III LIST	(ppm)	TLV (ppm)	Ref. Source **	
			67-64-1	No	1000	750	d	
ISOBUTANE / PROPANE BLEND			75-28-5	No	800	800	d	
			74-98-6	No	1000	1000	d	
SECTION 2 - PHYSICAL/CHEMICAL CHARACTERISTICS								
Boiling Point: N/A		Specific Gravity (H2O=1): Concentrate Only = < 1						
			Vapor Pressure (Non-Aerosols)(mm Hg and Temperature): N/A					
			Evaporation Rate ( = 1): N/E					
Solubility in Water: Soluble Water Reactive: No								
Appearance and Odor: Clear liquid with fragrance.  SECTION 3 - FIRE AND EXPLOSION HAZARD DATA								
ELAMMARILITY as por LI	ISA FLAME PROJECTION TEST (aerosols): flame		ito Ignition Temperatu		ammability Li	mite in Air by %	4 in Volume:	
projection with regular spray tip w/ capillary DT: projection 8"-14" with no flashback: CPSC: Not categorized as FLAMMABLE			Auto Ignition Temperature Flammability Limits in Air by % in Volume:  N/E					
FLASH POINT AND METHOD USED (non-aerosols): N/A SPECIAL FIRE FIGHTING PROCEDURES: Provide shielding for personnel. W							personnel. Wear	
, , , , , , , , , , , , , , , , , , ,			self-contained breathing apparatus. Cool containers with water fog to prevent					
EXTINGUISHER MEDIA: Foam, dry chemical, carbon dioxide, water. rupturing & spewing.								
Unusual Fire & Explosion Hazards: Do not expose aerosols to temperatures above 120°F or the container may rupture.								
SECTION 4 - REACTIVITY HAZARD DATA								
STABILITY [X] STABLE [] UNSTABLE HAZARDOUS POLYMERIZATION [] WILL [X] WILL NOT OCCUR								
Incompatibility (Mat. to avoid): Alkalis, oxidizing materials, amines. Conditions to Avoid: Open flame, welding arcs, heat.								
Hazardous Decomposition Products: CO, CO2.								
SECTION 5 - HEALTH HAZARD DATA								
PRIMARY ROUTES OF ENTRY: [X]INHALATION []INGESTION []SKIN ABSORPTION []EYE []NOT HAZARDOUS								
ACUTE EFFECTS Vapor concentrations around 1000 ppm may cause slight transient irritation to the upper respiratory tract.								
Inhalation: Excessive inhalation of vapors can be harmful and may cause headache, dizziness, asphyxia, anesthetic effects and possible unconsciousness.								
Eye Contact: Irritation	in Contact: May cause slight irritation.							
Ingestion: Possible chemical pneumonitis if aspirated into lungs. Nausea.								
CHRONIC EFFECTS: (Effects due to excessive exposure to the raw materials of this mixture) May cause mucous membrane irritation, overnight								
headache, and general weakness.  Medical Conditions Generally Aggravated by Exposure: May aggravate existing eye, skin, or upper respiratory conditions.								
EMERGENCY FIRST AID PROCEDURES								
Eye Contact: Flush with water for 15 minutes. If irritated, seek medical attention.								
Skin Contact: Wash with soap and water. If irritated, seek medical attention.								
Inhalation: Remove to fresh air. Resuscitate if necessary. Get medical attention.								
Ingestion: DO NOT INDUCE VOMITING. Drink two large glasses of water. Get immediate medical attention.								
SECTION 6 - CONTROL AND PROTECTIVE MEASURES								
Respiratory Protection (specify type): If vapor concentration exceeds TLV, use respirator approved by U.S. Bureau of Mines/ NIOSH for organic vapor.								
Protective Gloves: Latex, if skin easily irritated.  Eye Protection: Safety glasses recommended.								
Ventilation Requirements: Adequate ventilation to keep vapor concentration below TLV.								
Other Protective Clothing & Equipment: None								
Hygienic Work Practices: Wash with soap and water before handling food. Remove contaminated clothing.								
SECTION 7 - PRECAUTIONS FOR SAFE HANDLING AND USE								
Steps To Be Taken If Material Is Spilled Or Released: Absorb with suitable medium. Incinerate or landfill according to local, state or federal regulations. DO NOT FLUSH TO SEWER.								
Waste Disposal Methods: Aerosol cans when vented to atmospheric pressure through normal use, pose no disposal hazard.								
Precautions To Be Taken In Handling & Storage: Do not puncture or incinerate containers. Do not store at temperatures above 120°F.								
there programs are a consider the programs of								

her Precautions &/or Special Hazards: KEEP OUT OF REACH OF CHILDREN. Avoid food contamination. Avoid breathing vapors. Remove ignition sources.

We believe the statements, technical information and recommendations contained herein are reliable, but they are given without warranty or guarantee of any kind.

\*\* Chemical Listed as Carcinogen or Potential Carcinogen. [a] NTP [b] IARC Monograph [c] OSHA [d] Not Listed [e] Animal Data Only